

1200 New Jersey Avenue SE Washington, DC 20590

March 5, 2012

MR. DENNIS DICOSOLA DIRECTOR - CUSTOMER QUALITY AND WARRANTY RIDE CONTROL, LLC 950 MAPLELAWN TROY, MI 48084 NVS-215kjs 12E-007

SUBJECT: AFTERMARKET STRUT ASSEMBLIES

DEAR MR. DICOSOLA:

This letter serves to acknowledge Ride Control, LLC's (Ride Control) notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall campaign which will be conducted pursuant to Federal law for the equipment listed below.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

GABRIEL RIDE CONTROL/READYMOUNT G56944/9999 GABRIEL RIDE CONTROL/READYMOUNT G56945/9999 PARTSMASTER/READYMOUNT G68944/9999 PARTSMASTER/READYMOUNT G68945/9999 FORD/FOCUS/2000-2005 RIDE CONTROL/READYMOUNT 746641MT/9999 RIDE CONTROL/READYMOUNT 746646MT/9999

NHTSA Campaign Number: 12E-007 Mfg's Report Date: February 23, 2012

and amended report: February 28, 2012

Components: EQUIPMENT

Potential Number of Units Affected: 10,006

Summary:

RIDE CONTROL, LLC (RIDE CONTROL) IS RECALLING CERTAIN READYMOUNT ASSEMBLIES, P/N 746641MT AND 746646MT, WITH CORRESPONDING AFTERMARKET CUSTOMER PART NUMBERS: GABRIEL G56944 AND GABRIEL G56945, AND PRIVATELY BRANDED PARTSMASTER WITH PART NUMBERS G68944 AND G68945. THE READYMOUNT ASSEMBLIES WERE SOLD AS AFTERMARKET SERVICE EQUIPMENT FOR USE ON CERTAIN 2000 THROUGH 2005 FORD FOCUS VEHICLES. THESE ASSEMBLIES WERE ASSEMBLED WITH A NUT WITHOUT THE NECESSARY WASHER. THE ABSENCE OF THE WASHER CAN ALLOW THE READYMOUNT ASSEMBLY TO PULL APART THE TOP MOUNT.

Consequence:

IF THE ASSEMBLY SEPARATES DURING INSTALLATION, IT COULD RESULT IN INJURY TO THE INSTALLER. IF THE ASSEMBLY SEPARATES WHILE THE VEHICLE IS IN MOTION, IT COULD RESULT IN SECONDARY DAMAGE TO THE VEHICLE AND POSSIBLY RESULT IN A VEHICLE CRASH.

Remedy:

RIDE CONTROL WILL NOTIFY OWNERS AND WILL SET UP PROCEDURES TO INSPECT, REPAIR, AND/OR REPLACE THE AFFECTED PARTS WITHOUT CHARGE TO THE OWNER. THE SAFETY RECALL IS EXPECTED TO BEGIN DURING MARCH 2012. OWNERS MAY CONTACT RIDE CONTROL AT 1-800-999-3903.

Notes:

CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO HTTP://WWW.SAFERCAR.GOV.

Please provide the following information:

We have received Ride Control's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Ride Control must file a sample of the envelope which you intend to use to mail the recall notice to owners. The words "SAFETY", "RECALL", "NOTICE" in any order must be printed on the envelope in larger font than the customer's name and address.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within 30 days after the close of the calendar quarter in which the campaign was initiated. Thereafter, quarterly reports will be due on or before 30 days after close of the calendar quarter.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 1-202-366-5227, by email at Kelly.Schuler@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for the successful completion of this recall campaign.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigation

Enforcement